



# SNAG - APP

Mrs Jones Kitchen



**Address :**

1600 Pennsylvania Avenue

**Author:** Joe Blogs


**Attendees:**

Joe Blogs

**Date :** 2016/07/10

**Due Date :** 2016/07/20

The following document represents a record of defects, their location, description and their visual state. It also indicates where the responsibility lays as well as the time frames in which they are to be completed.



The reference plan above reflects positions of SNAG'S represented by numbers



**Bob Builder (Contractor)**

Due: 2016/07/20



**Before - Comment:**

Bottom drawer does not close properly.

*Layout*



**Bob Builder (Contractor)**

Due: 2016/07/20



**Before - Comment:**

Hinge loose

*Layout*



**Peter Plumb (Plumber)**

Due: 2016/07/20



**Before - Comment:**

Water meter broken

*Layout*

**Contractor**

Bob Builder  
555 12345677  
bob@buildercomq.com



**Plumber**

Peter Plumb  
555 12334567  
peter@pipq.com





# SNAG - APP

---

**Contractor**

---

**Project manager**

---

**Plumber**